


1.下記URLをブラウザで開いて下さい。

https://www.dropbox.com/sh/gihjypm8e9vxwik/AABAkNsSaM23TGmss7nC_Rqna?dl=0


2.「ダウンロード」をクリックしダウンロードして下さい。




3.ダウンロード後、ファイルを開いて下さい。

4. 「AccessPort137」 → 「AccessPort」 の順にファイルを開いて下さい。

5. 「AccessPort137」 → 「AccessPort」 の順に再度ファイル開いて下さい。

6.  をクリックし「Port」をCOM3に変更し「OK」をクリックして下さい。

7. バッテリーテスター（BST-860もしくはBST-560）をPCに接続し上下ボタンで「データ出力」を選び「OK」を押すと下記の様に表示されます。



The screenshot shows the 'AccessPort - COM3(9600,N,8,1) Opened' window. The main display area shows the following text:

```
Battery Test  
SOH: 60% 4650CA  
SOC: 65% 12.39V  
Internal R= 5.92mΩ  
Rated: 600CCA  
Select Input: EN  
REPLACE BATTERY  
|  
Cranking Test  
Cranking Time 2000mS  
Cranking Voltage NORMAL  
10.00V  
Charging Test  
LOADED 14.70V  
NO-LOADED 14.70V  
Ripple 10mV  
CHARGING NORMAL
```

The interface includes a menu bar (File, Edit, View, Monitor, Tools, Operation, Help), a toolbar with icons for file operations, and a status bar at the bottom showing 'Ready', 'Tx 0', 'Rx 286', and 'COM3(9600,N,8,1) Op'.

8. データをコピーしワードやエクセルなどにペーストした後、印刷して下さい。